National Transportation Safety Board NTSB ID: DEN02LA072 Aircraft Registration Number: N6283U FACTUAL REPORT Occurrence Date: 06/30/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80137 0811 **MDT** Watkins Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Mooney M20C Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On June 30, 2002, at 0811 mountain daylight time, a Mooney M20C, N6283U, owned and operated by the pilot, was substantially damaged when it landed gear up at Front Range Airport (FTG), Watkins, Colorado. The private pilot, the sole occupant aboard, was not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the local personal flight being conducted under Title 14 CFR Part 91. The flight originated from Front Range Airport at 0755.

In a telephone interview and reiterated in his accident report, the pilot said that the purpose of the flight was to practice touch-and-go landings. He said he "forgot to put the gear down" when he made his first approach to runway 26 and landed wheels up. Damage consisted of a bent propeller, scraped panels underneath the airplane, a broken antenna, and bent ribs.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA072

Occurrence Date: 06/30/2002

AVIATION Occurrence				e: Ac	cident									
Landing Facility/Approach In	formation	•												
Airport Name		,	Airport ID:	Aiı	rport Elevation	ı F	Runw	ay Used	Runwa	y Lengt	:h	Runv	way Width	
Front Range FTC			FTG		5512 Ft. MS	SL	26	6 8000				100		
Runway Surface Type: Asphalt		•				•					•			
Runway Surface Condition: Dry														
Type Instrument Approach: NONE	Ē													
VFR Approach/Landing: Touch ar	nd Go													
Aircraft Information														
Aircraft Manufacturer Mooney			1	Model/Series Serial M20C 2122								Number		
Airworthiness Certificate(s): Normal														
Landing Gear Type: Retractable	- Tricycle													
Homebuilt Aircraft? No	T I							er of Engines: 1		 ∷ 1				
=				Engine Manufacturer: Model/Series: Lycoming O-360-A1D						Rated Power: 180 HP				
- Aircraft Inspection Information								•						
Type of Last Inspection Dat				Pate of Last Inspection Time Sinc			nce Last Inspection			Airfran	Airframe Total Time			
Annual 10				10/2001 68.6 Hot					ours	rs 2528.5 Hours				
- Emergency Locator Transmitter (ELT) Information													
ELT Installed? Yes ELT Operated? No ELT Aided in Locating Accident Site? No														
Owner/Operator Information														
Registered Aircraft Owner	ss On File													
Roger L. Keithley	City							Stat	е	Zip Code 80220				
	Street A	treet Address												
Operator of Aircraft Same as Reg'd Aircraft Owner														
Same as Reg'd Aircraft Owner	City							Stat	e	Zip Code				
Operator Does Business As: Operator Designator Code:														
- Type of U.S. Certificate(s) Held:	None													
Air Carrier Operating Certificate(s)	:													
Operating Certificate: Operator Certificate:														
Regulation Flight Conducted Under: Part 91: General Aviation														
Type of Flight Operation Conducted	d: Personal													
]	FACTU	JAL REPO	ORT	- AVIATION	٧							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA072

Occurrence Date: 06/30/2002

AVIATION C					ce Type: Ac	cident								
First Pilot	Information			•					•					
Name	City					State	Date	e of Birth	Age					
On File On Fi											On File	On	File	55
Sex: M	wn				Certi	ficate Nur	nber:	On File	•					
Certificate(s): Private														
Airplane Rating(s): Single-engine Land														
Rotorcraft/Glider/LTA: None														
Instrument	Rating(s): None	e												
Instructor Rating(s): None														
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review?														
Medical Ce	rt.: Class 3	Medica	al Cert. Statu	s: Valid Med	dicalw/ wa	aivers/lir	n.		Date	e of Las	st Medical	Exam	: 02/2001	
									•					
- Flight Tim	Flight Time Matrix All A/C This Make and Model				Airplane Mult-Engine	Night	Night Ins Actual		Instrument		Rotorcra	ft	Glider	Lighter Than Air
Total Time	Total Time 139 59			139			4							
Pilot In Cor	nmand(PIC)	85	52	85										
Instructor												_		
Last 90 Day		14	14	14										
Last 30 Day		5	5	5							+	-		
Last 24 Hours 1 1 1 1								ology/ Do	rformod?) NI -			ad Dilat2 Na	
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? No														
Flight Pla	n/Itinerary													
	ght Plan Filed: N o	one												
Departure F	Point					Т	State		Airport Identifier De			Departure Time		Time Zone
Same as Accident/Incident Location									FTG		0755			MDT
Destination							State		Airport Ic	lentifier				
Local Flight									Airport Identifier					
Type of Cle	earance: Unkno	wn				•		•			·			
Type of Air	space: Class	E												
Weather	Information													
Source of I	Briefing: Unkno	own												
Method of Briefing: Unknown														
	FACTUAL REPORT - AVIATION Page 3													

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA072

Occurrence Date: 06/30/2002

Occurrence Type: Accident

	Occurrence Type. Accident												
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident S			dent Site		Direction Fron	n Accident Site	9	
DEN	0753	MDT	5431 Ft.	MSL				9 NM			310 Deg.	Mag.	
Sky/Lowes	st Cloud Condition: Clea	ar				Ft.	AGL	Condition o	on of Light: Day				
Lowest Ce	Lowest Ceiling: None Ft.					ility:	6	SM	Altir	meter:	30.17	"Hg	
Temperatu	1 °C	Wind	Direction: 220 Density Altitude: 7526 F							Ft.			
Wind Speed: 9 Gusts: Weather Cond							ccident S	ite: Visual C	Condi	itions			
Visibility (F	RVR): Ft.	Visibility (R	VV)	SM	Intensity	y of Preci	pitation:						
Restriction	s to Visibility: Haze												
Type of Precipitation: None													
Accident	Information												
Aircraft Damage: Substantial Aircraft Fire: None Aircraft Explosion None													
Classification: U.S. Registered/U.S. Soil													
- Injury Su	mmary Matrix	Fatal Se	rious Mino	or	None	TOTAL							
First Pi	ilot				1		1						
Second	d Pilot												
Studen	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants												
Other 0	Crew												
Passer	ngers												
- TOTAL A	ABOARD -				1		1						
Other 0	Ground						\neg						
- GRANI	O TOTAL -				1		1						

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DEN02LA072	NTSB	B II	D: I	DΕ	N0)2L	.A0	72
---------------------	------	------	------	----	----	-----	-----	----

Occurrence Date: 06/30/2002

Occurrence Type: Accident

Admir	nistrative	Information

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

John R Botterill Air Safety Inspector FAA Flight Standards District Office 26805 East 68th Avenue, Suite 200 Denver, CO 80249